





INJEÇÃO

SENSOR DE DETONAÇÃO

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GS5000	KIA / Hyundai: 39320-3C000	HYUNDAI: Sonata 3.3 2006>2010, Azera 3.3 2006>2010, Entourage 2007>2008, Santa Fé 3.3 2007>2009, Veracruz 2007>2010; KIA: Amanti 2007>2008, Optima 2.4 2001>2006
	GS5003	Ford: 1N1A-12A699-AA; Siemens/VDO: 330 001 003R	FORD: EcoSport 1.6 >04, Focus 1.8 Todos, Novo Fiesta 1.0/1.6 >04
	GS5004 comprimento do cabo: 67cm - 3 pinos	Bosch: 0 261 231 004, 0 261 231 038; VW: 034.905.377A, 053.905.377.2, 054.905.377A	FORD: Escort XR3 2.0i (Com LE - Jetronic) 01/93>, Royale, Versailles Ghia 2.0i Todos, Royale, Versailles GL 2.0i 09/93; GM: Kadett 2.0 GSI 11/91>, Monza Classic (MPFI) 92>, Omega, Suprema GLS 2.0 03/93>; VW: Gol GTi 2.0 09/88>12/92, Logus 2.0 92>96, Pointer 2.0 93>96, Quantum, Santana 2000 GLI/GLSI 09/93>, Quantum, Santana 2000i GLS >08/93, Santana EX 08/89>08/93
	GS5006 2 pinos	Bosch: 0 261 231 001, 0 261 231 006; GM: 90.510.281, Opel: 1 238 345, 6 238 341; Renault: 7 700 871 678; VW: 026.905.377.2	GM: Vectra 2.0 (MPFI), Vectra GSI 2.0 16V (SFI) 10/93>; RENAULT: R19 1.7 (Importado) 89>95; VW: Gol, Parati, Saveiro 1.6/1.8/2.0 Mi 96>, Polo Classic 1.8Mi 98>, Quantum, Santana 1.8/2.0 Mi 96>
	GS5007 comprimento do cabo: 50cm - 3 pinos	Bosch: 0 261 231 007, 0 261 231 033, 0 261 231 070, 0 261 231 071; Fiat: 7.669.123, 60.808.063	ALFA: 164 3.0 Todos; FIAT: Tempra - Turbo 04/94>, Tipo 1.6 (MPI) 12/95>, Uno 1.6R (MPI) 03/93>
	GS5046 2 pinos	Bosch: 0 261 231 045, 0 261 231 046; NTK: KNE05; VW: 030.905.377A	GM: Blazer, S10 2.2 (MPFI) 08/97>, Blazer, S10 2.4 (MPFI) 12/00>, Zafira 2.8 8/16V (MPFI) 04>; VW: Bora 2.0 00>, Gol, Parati 1.0 Mi 16V (Turbo) 00>, Golf 2.0 99>
	GS5075 comprimento do cabo: 31cm	Bosch: 0 261 231 075; Siemens/VDO: 330 001 005R; VW: 037.905.377, 037.905.377A	VW: Bora 2.0 12/00>08/02, Gol 1.0 8V, Parati 1.0 16V (Turbo) 06/02>, Gol, Parati 2.0 16V 95>, Golf A4 08/99>09/00, New Beetle 12/99>
	GS5077 2 pinos	Siemens/VDO: 330 001 002R; VW: 030.905.377C	AUDI: A3 1.8 05/00>; VW: Bora 2.0 09/02>, Gol, Parati, Saveiro 1.6/1.8/2.0 08/01>, Golf 1.8/2.0 03/00>, Polo 1.6/2.0 05/02>, Polo Sedan 1.6/2.0 11/02>
	GS5079 comprimento do cabo: 57cm - 2 pinos	Bosch: 0 261 231 079; GM/Opel: 90.511.177	GM: Astra 2.0 16V 02/99>, Vectra 2.0 (MPFI) 07/98>12/02, Vectra 2.2 16V (MPFI) 04/96>11/97, Vectra 2.2 16V (SFI) 01/03>06/05, Vectra CD 2.0 16V (SFI) 12/97>06/05, Omega 2.5i (Ecotec) 01/94>11/00, Omega 3.0i (Ecotec) 01/99>02/01
	GS5095 comprimento do cabo 42cm - 3 pinos	Bosch: 0 261 231 095; Fiat: 60.592.752	FIAT: Marea, Marea Weekend 2.0i 20V 05/98>, Marea, Marea Weekend 2.0i 20V (Turbo) 05/98>
	GS5144 comprimento do cabo 42cm - 3 pinos	Bosch: 0 261 231 144; Fiat: 46.525.288	FIAT: Marea, Marea Weekend 2.4i 20V 01>

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GS5152 2 pinos	Bosch: 0 261 231 148; Fiat: 46.538.111, 46.815.152, 55.190.562; NTK: KNE11, KNE21	FIAT: Brava 1.6 16V (MPI) 02>, Palio 1.0/1.3 16V, Palio Weekend 03/00>, Palio 1.0 8V, Palio 1.6 16V (MPI - Fire) 01>, Siena 1.0/1.3 16V, Strada 1.3 16V (Fire) 03/00>, Uno 1.0 8V (MPI - Fire) 02>, Uno Furgoneta 2P 1.3 8V (MPI - Fire) 03>04
	GS5176	Bosch: 0 261 231 176; GM: 93 399 899; Fiat: 55186669	GM: Agile 1.4 Flex 2009>, Astra 2.0 MPFI Flexpower 2004>, Astra Sedan 2.0 MPFI Multipower 2004>2006, Blazer 2.4 MPFI Flexpower 2007>, Corsa 1.0 VHC Flexpower 2005>2008, Montana 1.4 Econo.Flex 2010>, S-Series S10 2.4 MPFI Flexpower 2007>, Vectra 2.0 Flexpower 2005>2009, Vectra 2.0 Flexpower Next Edition 2009>2011, Vectra 2.4 16V Flexpower 2005>2009, Vectra Hatch 2.0 Flexpower 2007>2011, Zafira 2.0 MPFI Flexpower 2004>; FIAT: Idea 1.4 Flex 2005>2010, Palio 1.0 MPI 8V 2003>2005, Palio 1.0 MPI / 8V Flex 2006>2009, Palio II 1.0 MPI 8V Flex 2005>2008, Palio II 1.4 MPI 8V Flex 2005>2008, Palio Weekend II 1.4 MPI 8V Flex 2005>2010, Siena Fire 1.0 MPI Flex 2005>2006, Siena II 1.0 MPI 8V 2004>2005, Siena II 1.0 MPI 8V Flex 2005>2010, Siena II 1.4 MPI 8V Flex 2005>2010, Siena II 1.4 MPI 8V Tetrafuel 2006>, Siena II Fire 1.0 MPI Flex 2006>2009, Strada 1.4 MPI 8V Flex 2005>2008, Strada II Fire 1.4 MPI 8V Flex 2006>2009, Uno Mille II 1.0 MPI Flex 2005>2008
	GS5197	Bosch: 0 261 231 197; BMW: 13627552114; Citroën/ Peugeot: V755211480, 1920 LT; Mini: 13627552114	BMW: 116i/118i 2010->, 116i 2011->316i 2013>2016; MINI: Mini Cooper S 2010>2016, Mini Cooper S ALL4 2013>2016, John Cooper Works 2008>2013; CITROËN: C4 Pallas Sedan 1.6 exclusive 2013->, C4 Lounge 1.6 THP exclusive 2013->, C5 1.6 THP exclusive 2011->, DS3 1.6 THP 2012>2015, DS3 1.6 turbo 2014>2015, DS4 1.6 THP 2012>2015, DS5 1.6 THP 2012>2015; PEUGEOT: 308 1.6 THP 165 2010>2012, 408 1.6 THP 165 Griffé 2012>, 508 1.6 THP 165 2012>, 3008 Monovolume 1.6 THP 2010>, 3008 Monovolume 1.6 Griffé Turbo 2014>, 3008 SUV 1.6 THP 165 Griffé Pack 2017>, RCZ 1.6 Turbo High Pressure 16V 2011>2015, DS5 2015>
	GS5327	Delco: 2133944; GM: 12600327	GM: Celta 1.0 4Cil 8v Flex 2014>2016, Celta 1.4 4Cil 8v Flex 2014>2016, Cobalt 1.4 4Cil 8v Flex 2017 >2020, Cobalt 1.8 4Cil 8v Flex 2017>2020, Corsa 1.4 4Cil 16v Flex 2014>, Express 1500 4.3 V6 12v Gasolina 2008>2014, Montana 1.4 4Cil 8v Flex 2015>2020, Onix 1.0 4Cil 8v Flex 2013>2021, Onix 1.4 4Cil 8v Flex 2013>2021, Prisma 1.0 4Cil 8v Flex 2013>2021, Prisma 1.4 4Cil 8v Flex 2013>2021, Savana 1500 4.3 V6 12v Gasolina 2008>2014, Sierra 1500 4.3 V6 12v Gasolina 2007>2013, Silverado 1500 4.3 V6 12v Gasolina 2007>2013, Spin 1.8 4Cil 8v Flex 2020
	GS5377 comprimento do cabo: 34cm	VW: 06A.905.377A	VW: Golf 1.6/1.6 SR 99>
	GS5460	Fiat: 55223460	FIAT: Argo HGT 1.8 2017>, Bravo 1.8 16V flex 2011>, Doblô 1.8 16V flex 2010>, Grand Siena 1.6 16V flex 2013>, Idea 1.6/1.8 16V flex 2011>, Palio 1.6 16V flex 2012>, Punto 1.6/1.8 16V flex 2013>, Siena 1.6 16V flex 2011>2012, Strada 1.8 16V flex 2011>2012, Toro 1.8 16V flex 2016>; JEEP: Renegade 1.8 16V flex 2015>
	GS5477	Audi / VW: 06A905377B	AUDI: A3 1.6 1997>2006, A3 1.8 20V 1996>2006, A3 1.8 turbo 1999>2006, A3 1.8T 2000>2006, TT 1.8t 1998>2006; VW: Golf 1.8T 1999>2002
	GS5480	Citroën/ Peugeot: 9660524480, 9632754980; Mini: 1362 7535 067	PEUGEOT: 206 1.4/2.0 16V 1998>, 207 1.4 16V 2007>, 208 1.4/1.6 16V 2012>, 307 2.0 16V 2000>, 308 1.4/1.6 16V 2007>, 406 1.8/2.0 2000>2004, 407 1.8/2.0 16V 2004>, 508 1.6 16V 2010>; CITROËN: C3 1.4/1.6 16V 2009>, C3 picasso 1.4/1.6 16V 2009>, C4 1.6/2.0 16V 2004>, C4 picasso 1.6/2.0 2008>, C5 1.8/2.0 16V 2001>, DS3 1.4/1.6 16V 2010>, DS4 1.6 16V 2011>, Xsara 2.0 16V 2000>2005, Xsara Picasso 2.0 16V 2003>; MINI: One 2011>2013, Cooper 2009>2010, Cooper 2010>2016
	GS5530 2 pinos	Honda: 30530-R1A-A01	HONDA: Civic, CR-V, HR-V, Acoord 2015>2017
	GS5577 comprimento do cabo: 36cm - 3 pinos	Audi/VW: 06A.905.377	AUDI: A3 1.8/1.8 Turbo 01>; VW: Bora, Golf 1.8 01>

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GS5740 comprimento do cabo: 37cm - 3 pinos	Fiat: 46.522.740; NTK: KNE03A	FIAT: Brava, Marea 1.8 16V 00>
	GS5832 comprimento do cabo: 20cm - 3 pinos	Fiat: 60.602.832; NTK: KNE03	FIAT: Palio, Siena 1.0/1.5/1.6 8V, 1.6 16V (MPI) 96>00, Uno 1.5 (MPI) 97>