



INJEÇÃO

SENSOR DE ROTAÇÃO

## GUIA DE ABREVIÇÕES

+	TERMINAL POSITIVO DO SENSOR	S	MALHA DE ATERRAMENTO DO CABO DO SENSOR (GROUND)
-	TERMINAL NEGATIVO DO SENSOR		

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	<b>GS8000</b>	<b>Audi/ VW:</b> 050906433; <b>Valeo:</b> 254161	<b>AUDI:</b> A4 1994>2001, A4 Avant 1994>2002; <b>VW:</b> Passat 1996>2001, Passat Variant 1997>2001
	<b>GS8001</b>	<b>Hyundai:</b> 391802B000, 391802B010; <b>Bosch:</b> 0 986 280 497; <b>Valeo:</b> 366133	<b>HYUNDAI:</b> Elantra sedan 1.8 GLS 2011>, HB20 1.6 Premium Confort Plus 2013>2019, i30 1.8 GLS 16V 2014>; <b>KIA:</b> Cerato II 1.6 16V Sport 2009>2013
	<b>GS8003</b>	<b>Honda:</b> 37500-PNA-003, 37500-PNB-003, 15503L23; <b>Denso:</b> 15512225	<b>Honda:</b> Fit 1.4/1.5 2004>2008, New Ciivc 2.0 2006>2011, CRV 2.0 2002>2009
	<b>GS8011</b>	<b>Toyota:</b> 90919-05011; <b>Denso:</b> DCPS-0102	<b>TOYOTA:</b> Corola E11 1.6 XLI S/D 1998>2002
	<b>GS8013</b>	<b>Bosch:</b> 0.261.210.207, 0.261.210.208; <b>VW:</b> 06A906433K, 030906433K	<b>VW:</b> Gol III (Power) 1.0 16V MI 2000> Gol, Parati III 1.0 16V MI (TURBO/ASPIRATE) 04/00>02, Gol, Parati, Saveiro 1.6, 1.8 (Flex) 02>Gol II Special 1.0Mi 8V 02>05
	<b>GS8015</b>	<b>Honda:</b> 37500-PLC-015; <b>Denso:</b> 00601D0	<b>Honda:</b> Civic 1.7 2001>2005
	<b>GS8030</b>	<b>Toyota:</b> 90919-05030, 90080-19013, 02960-00755; <b>Lotus:</b> A131E6216S	<b>TOYOTA:</b> Corola sedan 1.6 XLI S/D 2002>2008, Corola sedan 1.6 VVTI 2008>2011
	<b>GS8033</b>	<b>Nissan:</b> 23731-AW410, 23731-EC00A, 23731-EC01A, 949979-033	<b>Nissan:</b> Frontier Sel 2.5 Diesel, Frontier 2.5 CD SE 2008>, Frontier 2.5 4WD 2007>2012, Frontier 2.5 LE 4WD 2005>, Pathfinder 2.5 2005>2009
	<b>GS8047</b>	<b>Toyota:</b> 90919-05047, 90919-05067	<b>Toyota:</b> Corolla, RAV4, Camry, Corona, Previa
	<b>GS8050</b>	<b>Hyundai:</b> 39310-38050; <b>Kia:</b> 39310-38050; <b>Mitsubishi:</b> J5T23071A; <b>Volvo:</b> 30874179; <b>Mazda:</b> MD 327107	<b>Hyundai:</b> Santa Fé 2.4 2001>, Sonata 1999>; <b>Kia:</b> Sorento, Picanto, Optima 2001>; <b>Suzuki:</b> Vitara 1.6/ 2.0 1999>; <b>GM:</b> Tracker 1.6/ 2.0 1999>; <b>Volvo:</b> S40, V40 1995>2003

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	<b>GS8076</b> 3 PINOS	<b>Cummins:</b> 5594275; <b>New Holland:</b> 87352952, 90418076	<b>NEW HOLLAND:</b> Plataforma / Combine: CR9040, CR9060, CR9065, Trator / Tractor: T8010, T8020, T8030, T8040, T8050, T9010, T9020, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305, Motoniveladora / Motor Grader: 845 DHP
	<b>GS8097</b> 2 PINOS	<b>Renault:</b> 8200746497, A2C53255629	<b>RENAULT:</b> Sandero 1.6 2007>2015, Duster 1.6 2011>2016, Scenic 1999>2010, Kangoo 1.6 2002>2018, Megane 1.6 1997>2014
	<b>GS8099</b>	<b>Dodge:</b> 5093101AA, 5179099AA, 5179099AB	<b>DODGE:</b> Ram 5.9 Turbo Diesel 2500 2003>2005
	<b>GS8104</b>	<b>Fiat:</b> 7762252, 7762282; <b>Bosch:</b> 0.261.210104; <b>Kia:</b> 0K9A018891; <b>VDO:</b> 324003030R; <b>Hyundai:</b> 3965042110	<b>Fiat:</b> Palio, Strada, Siena, Weekend 1.4, 1.6 mpi 96>02, Punto 1.4 93>99; <b>Hyundai:</b> H200 Diesel, H1 Starex 97>04; <b>Kia:</b> Sportage Gasoline 84>03/ Diesel 97>03
	<b>GS8133</b> 2 PINOS INDUTIVO	<b>VW:</b> 06H906433; <b>Audi:</b> 06H906433; <b>Bosch:</b> 0 986 280 496	<b>VOLKSWAGEN:</b> Amarok 2.0 2010>2012, CC 2.0 2012>2017, Fusca 2.0 2012>2016, Jetta 2.0 2011>2014, Passat 2.0 2009>2011, Tiguan 2.0 2008>2011, EOS 2.0 2009>2011 <b>AUDI:</b> A3 2.0 2008>2014, A4 2.0 2008>2015, A5 1.8 2015>2016, A5 2.0 2009>2017, Q5 2.0 2009>2012, TT 2.0 2006>2010
	<b>GS8145</b>	<b>Mitsubishi:</b> MR985145, J5T35171	<b>Mitsubishi:</b> Pajero Full 3.5 V6, Pajero Sport 3.8 2004>2012, Galant 3.8 2004>2009, Eclipse 3.8 V 2007>2012, rion 3.5 V6 Flex 2008>2015
	<b>GS8150</b>	<b>Kia/ Hyundai:</b> 39180-37150, 39180-37200	<b>HYUNDAI:</b> Santa Fé 2.7 V6 4x4 2001>2005, Sonata 2.5 V6 24V 1998>2001, Tucson 2.7 Tração integral 2004>2010; <b>KIA:</b> Sportage 2.7 V6 4WD 2004>2010
	<b>GS8151</b>	<b>Bosch:</b> 0 261 210 151, 0 281 002 662, 0 281 002 742; <b>Volvo:</b> 20513343	<b>VOLVO:</b> FH (motores D13) 2006>2015
	<b>GS8161</b>	<b>GM:</b> 10456161; <b>Delphi:</b> SS10213	<b>GM:</b> Omega Australiano 3.8 V6 98>
	<b>GS8170</b>	Mercedes Benz: 0031532828, 0031532728; <b>Chrysler:</b> 05080350AA, 05080352AA; <b>Mitsubishi:</b> MN-960274, MN-960372	<b>Mercedes:</b> Classe A - A160, A190, Classe C - C230, C240, C240 automatic, C280, C32AMG, C320, C320 4matic, C43AMG, Classe 500 - CL500, CL55AMG, CL600, CLK320, CLK430, Classe E - E430, E500, E55AMG, Classe ML - ML320, ML350, ML430, ML500, Classe S - S430, S500, S600, SL500, SL55amg, SL600, SLK230, SLK32amg, SLK320
	<b>GS8171</b>	<b>Mitsubishi:</b> MR560132; <b>Denso:</b> J5T20171	<b>Mitsubishi:</b> Pajero TR4 2.0, Pajero iO 1.8, Lancer 99>07

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	<b>GS8178</b>	<b>Bosch:</b> 0261210178; <b>VW:</b> 078906433B	<b>Audi:</b> A4 2.4 Avant quattro 1998>2001 / 2.8 1998>2000 / 2.8 Avant quattro 1999>2001 / 3.0 Avant quattro Cabriolet 2001>2004, A6 2.4 Avant quattro 1997>2005 / 2.8 Avant quattro 1998>2001 / 3.0 2001>2004, TT 1.8 T Coupe quattro 2002>2006 / 1.8 T Roadster quattro 2002>2006; (Todos Gasolina); <b>VW:</b> Golf IV 2.0 2007>2008, New Beetle 2.0 2006>2010, Passat 2.8 1997>2005 / 2.8 Variant Syncro 1998>2000 (Todos Gasolina)
	<b>GS8180</b>	<b>Peugeot:</b> 9640316180	<b>Peugeot:</b> 206 1.0 16V 2001>2005
	<b>GS8200</b>	<b>Hyundai/ KIA:</b> 39180-25200, 39180-25300	<b>Hyundai:</b> Santa Fé 2.4 GLS / 4x4 2010>2014, Sonata 2.0/2.4 2006>2015, Tucson 2010>2015, ix35 2.0 GLS / GLS 4WD 2010>; <b>Kia:</b> Carens 2.0 CVVT 2006>2014, Magentis 2.0 EX 2006>2010, Sportage 2.0 LX CVVT AWD 2011>, Sorento 2.4 16v 2010>2015
	<b>GS8206</b> comprimento do cabo: 46cm	<b>Magneti Marelli:</b> 4820083010; <b>Fiat:</b> 4460206	<b>FIAT:</b> Elba CSL 4P 1.6 8V (SPI - gasolina) 94>96 / Weekend 2P/4P 1.5 8V (SPI - álcool/gasolina) 92>96, Fiorino / Furgão/ Pick-up 2P 1.0 8V (SPI - gasolina) 96 / Furgão/ Pick-up 2P 1.3 8V (SPI - gasolina) 94>95 / Furgão 2P 1.5 8V (SPI - álcool/gasolina) 94>96 / Pick-up 2P 1.5 8V (SPI - álcool/gasolina) 94>95 / Pick-up LX 2P 1.6 8V (SPI - gasolina) 94>96 / Pick-up Trekking 2P 1.5 8V (SPI - gasolina) 96 / 2P 1.5 8V (MPI - gasolina) 97>98 / MTV 2P 1.5 8V (MPI - gasolina) 97 / Pick-up Working 2P 1.5 8V (SPI - gasolina) 96, Prêmio CS 4P 1.5 8V (SPI - álcool/gasolina) 93>94 / CSL 4P 1.6 8V (SPI - gasolina) 94>96 / S 2P 1.5 8V (SPI - gasolina) 92>93 / SL 4P 1.5 8V (SPI - gasolina) 92, Uno CS 2P/4P 1.5 8V (SPI - álcool/gasolina) 93>94 / Furgoneta 2P 1.5 8V (SPI - álcool/gasolina) 94>96 / Mille City 4P 1.0 8V (SPI - gasolina) 99>00 / Eletronic 2P/4P 1.3 8V (SPI - gasolina) 93>95 / ELX 2P/4P 1.3 8V (SPI - gasolina) 94>95 / EP 2P/4P 1.0 8V (SPI - gasolina) 96 / EX 2P/4P 1.0 8V (SPI - gasolina) 98>00 / IE 2P 1.0 8V (SPI - gasolina) 94 / Smart 2P/4P 1.0 8V (SPI - gasolina) 00>01 / Smart City 4P 1.0 8V (SPI - gasolina) 00>01 / SX 2P/4P 1.0 8V (SPI - gasolina) 97>98 / SX Young 2P 1.0 8V (SPI - gasolina) 98>99, Uno S 2P 1.5 8V (SPI - álcool/gasolina) 92>94
	<b>GS8215</b>	<b>VDO:</b> 324 005 001R; <b>Ford:</b> 1 110 834, YS6A-6C315-AB	<b>FORD:</b> Courier, Fiesta, Ka 1.0/1.3 (Endura) 96>99, EcoSport, Novo Fiesta 1.6 (Zetec RoCam) 03 > 09
	<b>GS8220</b>	<b>Nissan / Infiniti:</b> 23731-1S700	<b>NISSAN:</b> Pathfinder 3.3 V6 4WD 1997>2002
	<b>GS8243</b>	<b>GM:</b> 55567243; <b>Valeo:</b> 366506	<b>GM:</b> Cruze Hatch Sport Lt 1.8 Flex- Automatico 2012>2016, Cruze Hatch Sport Lt 1.8 Flex- Manual 2012>2016, Cruze Hatch Sport Lt 1.8 Flex- Automatico 2012>2016, Cruze Hatch Sport Lt 1.8 Flex- Manual 2012>2014, Cruze Sedan Lt 1.8 Flex- Automatico 2012>2016, Cruze Sedan Lt 1.8 Flex- Manual 2012>2016, Cruze Sedan Lt 1.8 Flex- Automatico 2012>2016, Sonic Hatch Lt 1.6 Flex- Manual 2012>2014, Sonic Hatch Lt 1.6 Flex- Automatico 2012>2014, Sonic Hatch Lt 1.6 Flex- Manual 2012>2014, Sonic Sedan Lt 1.6 Flex- Manual 2012>2014, Sonic Sedan Lt 1.6 Flex- Automatico 2012>2014, Sonic Sedan Lt 1.6 Flex- Manual 2012>2014, Tracker Freeride 1.8 Flex- Manual 2014>2016, Tracker Ls 1.8 Flex- Manual 2014>2016, Tracker Lt 1.8 Flex- Automatico 2014>2016, Tracker Lt 1.8 Flex- Manual 2014>2016, Tracker Lt 1.8 Flex- Automatico 2014>2016, Tracker Lt 1.8 Flex- Manual 2014>2016
	<b>GS8251</b> comprimento do cabo: 42cm	<b>Bosch:</b> 0 281 002 102; <b>Fiat:</b> 77662510	<b>FIAT:</b> Brava 1.4 12V 94 > 98, Coupé 2.0 20V 94 > 98, Marea Turbo 98 > 07, Marea Weekend ELX 4P 2.0i 20V (MPI - gasolina) 142 CV 96 > 00, Marea, Marea Weekend HLX 4P 2.0i 20V (MPI - gasolina) 142 CV 96 > 00
	<b>GS8269</b>	<b>Renault:</b> 7700101970, 7700103069A; <b>Bosch:</b> 0 986 280 410	<b>RENAULT:</b> Clio II 1.6i / 1.6i 16V 1999 / 2007, Twingo 1.0 16V, Kangoo 1.6i 2001 >, Mégane 1.6i / 2.0 1996 / 2002, Mégane II 1.6i 16V, Scénic I / II 1.6 16V 1999 >

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	<b>GS8279</b>	<b>Cummins:</b> 2872279; <b>CNH:</b> 84274595, 87341787	<b>NEW HOLLAND:</b> T8050; <b>CASE:</b> 2399, 2688, 2799; <b>VW:</b> Costalation 19-320E, 25-320E
	<b>GS8282</b>	<b>Renault:</b> 7700101970, 7700103069A; <b>Bosch:</b> 0 986 280 410	<b>Mitsubishi:</b> Pajero Sport 2.8, Pajero Full 3.2, L200 Triton 3.2
	<b>GS8290</b> comprimento do cabo: 48,5cm	<b>Magneti Marelli:</b> 4820084010; <b>Fiat:</b> 5944390, 7588435, 7604582, 7646975	<b>FIAT:</b> Ducato TD 2.8 8V (MPI - gasolina) 00 >, Tempra 2.0 16V (MPI - gasolina) 93 > 99, Tempra 2.0 8V (SPI - gasolina) 94 >, Uno Turbo 1.4 8V (MPI - gasolina) 94
	<b>GS8302</b> comprimento do cabo: 73,5cm * Sem ar condicionado	<b>Bosch:</b> 0 261 210 102, 0 261 210 115; <b>Fiat:</b> 7756925, 7799033; <b>New Holland:</b> 8203048	<b>FIAT:</b> Tipo 2P/4P 1.6 8V (SPI - gasolina), Tempra 1.6ie 1993 / 1996
	<b>GS8303</b> comprimento do cabo: 64cm	<b>Bosch:</b> 0 261 210 103, 0 261 210 118; <b>Fiat:</b> 7756924, 7799032	<b>FIAT:</b> Elba CSL 1.6 (MPI) Todos, Fiorino, Pick-up 1.6 (MPI) 95>96, Tempra 1.6ie 04/93>12/96, Tipo 1.6 ie (gasolina) c/ AC 93>95, Tipo 1.6 8V (MPI - gasolina) c/ AC 96>97, Uno 1.6 8V (MPI - gasolina) 95>96
	<b>GS8305</b>	<b>Ford:</b> 94BF-6C315-AA, 948F-6C315-AA, 92BF-6C315-A1F, 928F-6C315-A1F, F5RZC315AA;	<b>Ford:</b> Escort 91>, Fiesta 1.0, 1.4 95>, Focus 98>04, KA 1.3 96>08, Mondeo 96>00, Transit 00>06;
	<b>GS8307</b>	<b>Fiat:</b> 5033307AC	<b>Fiat:</b> Freemont 2.4; <b>Dodge:</b> Journey 2.0 / 2.4; <b>Jeep:</b> Compass 2.0 16V 2011>
	<b>GS8315</b> comprimento do cabo: 99cm	<b>Bosch:</b> 0 261 210 030; <b>GM:</b> 90 213 515, 90 451 441; <b>VDO:</b> 324 003 007R	<b>GM:</b> Astra, Sedan 2.0 (MPFI) 09/94>12/96, Astra 2.0i 09/91>02/98, Astra, Sedan 2.0 (MPFI) 09/03>, Astra, Sedan 2.0 (MPFI - Flexpower) 04/04>, Blazer, S10 2.2 (MPFI) 08/97>04/00, Blazer, S10 2.4 (MPFI) 05/00>01/07, Calibra 2.0i/2.0i turbo 06/90>03/97, Calibra 2.0 16V 10/93>03/96, Omega, Suprema GLS 2.0 (MPFI) 09/92>12/95, Omega 1.8/1.8i/2.0i 09/86>03/94, Vectra 1.8i 03/90>08/95, Vectra CD 2.0 8V, Vectra GLS 2.0 (MPFI) 10/93>03/96, Vectra GSI 2.0 16V 10/93>03/96, Zafira 2.0 (MPFI - Flexpower) 03/04>
	<b>GS8319</b> comprimento do cabo: 48cm	<b>Bosch:</b> 0 261 210 119; <b>Fiat:</b> 7790917	<b>FIAT:</b> Marea, Marea Weekend 2.0i 20V (Turbo) 05/98>
	<b>GS8321</b>	<b>Jeep:</b> 4897321AA, 56027865AC, 56027868, 56027868AB, 56027868AC, 56027869AC	<b>JEEP:</b> Jeep Grand Cherokee Laredo 4.0 1997>2004, Jeep Grand Cherokee Limited 4.0 1997>2004, Wrangler 4.0 Sport 4x4 1997>2007

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	<b>GS8324</b> comprimento do cabo: 61,5cm	<b>Bosch:</b> 0 261 210 124; <b>Fiat:</b> 77872650, 46774532, 55187333, 7777960	<b>FIAT:</b> Fiorino Furgão Fire 2P 1.3 8V (MPI - gasolina) 03/00>, Palio EX Fire 2P/4P 1.0 8V (MPI - gasolina) 01>03, Palio EX Fire 2P/4P 1.3 8V (MPI - gasolina) 03, Palio EX Fire Flex 2P 1.0 8V (MPI - álcool/gasolina) 06>, Palio ELX Fire Flex 4P 1.0 8V (MPI - álcool/gasolina) 06>, Palio ELX Fire Flex 4P 1.3 8V (MPI - álcool/gasolina) 04>05, Palio Fire 2P/4P 1.0 8V (MPI - gasolina) 03/00>04, Palio Fire Flex 2P/4P 1.0 8V (MPI - álcool/gasolina) 06>, Palio Penta Fire 4P 1.0 8V (MPI - gasolina) 03, Palio Weekend EX Fire 4P 1.3 8V (MPI - gasolina) 03>04, Palio Weekend ELX Fire Flex 4P 1.3 8V (MPI - álcool/gasolina) 05, Palio Young Fire 2P/4P 1.0 8V (MPI - gasolina) 02, Siena ELX Fire Flex 4P 1.0 8V (MPI - álcool/gasolina) 02>03 / 4P 1.3 8V (MPI - álcool/gasolina) 06>, Siena EX Fire 4P 1.3 8V (MPI - gasolina) 03>04, Siena Fire 4P 1.0 8V (MPI - gasolina) 05, Siena Fire Flex 4P 1.0 8V (MPI - álcool/gasolina) 06>, Strada Fire 2P 1.3 8V (MPI - gasolina) 03>05, Strada Fire estendida 2P 1.3 8V (MPI - gasolina) 03>05, Uno Furgoneta Fire 2P 1.3 8V (MPI - gasolina) 03>, Uno Mille Fire 2P/4P 1.0 8V (MPI - gasolina) 02>06, Uno Mille Fire Flex 2P/4P 1.0 8V (MPI - álcool/gasolina) 06>
	<b>GS8328</b> comprimento do cabo: 100cm	<b>Bosch:</b> 0 261 210 128; <b>GM:</b> 92062490, 93232413; <b>VDO:</b> 324003007R	<b>GM:</b> Astra, Sedan 1.8 (MPFI) 98 >, Astra, Sedan 2.0 (MPFI) 98>, Astra Sedan 2.0 (MPFI - Multipower) 04 >, Blazer, S10 2.4 (MPFI - Flexpower) 07 >, Vectra 2.0 (Flexpower) 05 > Vectra B 2.0 (MPFI) 96 / 98 e 03 / 05, 2.2 (MPFI) 98 > 02, Vectra C 2.0 Flex 05 >, Vectra Hatch 2.0 (Flexpower) 07 >, Zafira 2.0 (MPFI) 01 > 04
	<b>GS8331</b> comprimento do cabo: 44cm sem ar-condicionado	<b>Fiat:</b> 46445731; <b>Magneti Marelli:</b> 4820171010	<b>FIAT:</b> Fiorino Furgão, Pick up 1.5 8V (MPI - álcool/gasolina) 97>04 /, Palio 1.5 8V (MPI - álcool) 96 > 00 e 03 > 04, Palio 1.0 8V MPI 96 > 00, Young 1.0 8V 01 > 02, Weekend 1.5 8V MPI 97 > 00 Weekend 1.0 8V MPI 99 > 00, Siena 1.5 8V MPI 99 > 00 e 03 > 04, Strada 1.5 8V MPI 00 > 04, Uno, Mille, Furgoneta 1.5 8V MPI 97 > 04, Mille 1.6 8V MPI 99 > 04
	<b>GS8332</b> comprimento do cabo: 73cm	<b>Magneti Marelli:</b> 1040211101; <b>Fiat:</b> 55187332, 55189515, 46479975	<b>FIAT:</b> Brava SX, ELX 4P 1.6 16V (MPI - gasolina) 00 > 03, Doblo Cargo 2P 1.6 16V (MPI - gasolina) 02 > 03 / ELX 2P 1.6 16V (MPI - gasolina) 02 > 03, Marea, Marea Weekend SX 4P 1.6 16V (MPI - gasolina) 06 >, Palio 1.6 16V (MPI - gasolina) 96 > 03 / 1.6 16V (MPI - gasolina) 96>00 / ELX 1.6 16V 01>03 / Stile 1.6 16V (MPI - gasolina) 01>02 / Adventure 1.6 16V (MPI - gasolina) 01>03 / Weekend 1.6 16V (MPI - gasolina) 97>98 / Weekend Sport 1.6 16V (MPI - gasolina) 97>00 / Weekend Stile 1.6 16V (MPI - gasolina) 97>03, Siena EL 1.6 16V (MPI - gasolina) 98 / ELX 1.6 16V (MPI - gasolina) 01>03 / HL 1.6 16V (MPI - gasolina) 98 / Sport MTV 1.6 16V (MPI - gasolina) 98 / Stile 1.6 16V (MPI - gasolina) 98>99, Strada LX 1.6 16V (MPI - gasolina) 99>00 / LX estendida 1.6 16V (MPI - gasolina) 00>02 / Working estendida 1.6 16V (MPI - gasolina) 01 / Working 1.6 16V (MPI - gasolina) 02 / Adventure 1.6 16V (MPI - gasolina) 02
	<b>GS8337</b> comprimento do cabo: 21cm	<b>Bosch:</b> 0 261 210 137; <b>Renault:</b> 770085931 / 7702218699	<b>RENAULT:</b> Clio 1.6i 96 > 97, R19 Sedan 1.6i 93 > 00
	<b>GS8339</b> comprimento do cabo: 88,5cm   chicote longo	<b>GM:</b> 90 483 739; <b>Bosch:</b> 0 261 210 048	<b>GM:</b> Corsa, GSI, Sedan, Wagon 1.0, 1.6 16V 97 > 02, Corsa 1.6 8V 95>01, Tigra 1.6 16V 96 >
	<b>GS8341</b>	<b>Bosch:</b> 0 986 280 403; <b>Renault:</b> 7700720341, 7700725811, 7700728639, 7700732300, 7700739792	<b>RENAULT:</b> 11 1.4/ 1.7 1985>1995, 9 1.4 19885>1995, Clio 1.2/ 1.4/ 1.7 1990>1998, Espace I 2.0 8V 1988>1990, Express 1.2 8V/ 1.4 8V 1985>, R19 1.2/ 1.4/ 1.7 1989>, R21 1.4/ 1.6/ 1.7 1986>1994, R25 2.0/ 2.2 8V 1984>1992, Trafic 1.7 8V 1992>1994
	<b>GS8342</b> comprimento do cabo: 66cm	<b>GM:</b> 90 451 442; <b>VDO:</b> 324003001R	<b>GM:</b> Astra 1.8 16V 03>, Celta 1.0/1.4 (MPFI) 01>, Corsa 1.4/1.6 (EFI - MPFI) 95>, Corsa 1.0/1.4/1.6 (MPFI - gasolina/Flexpower) 02>, Corsa 1.8 (MPFI - gasolina) 04>, Meriva 1.8 8V (MPFI - gasolina/Flexpower) 03>, Montana 1.8 8V (MPFI - gasolina/Flexpower) 04>
	<b>GS8348</b> comprimento do cabo: 58cm	<b>Bosch:</b> 0 261 210 147, 0 261 210 148 ; <b>VW:</b> 06A906433C	<b>AUDI:</b> A3 1.6, 1.8, 1.8 20V Turbo 96 / 06, A4, A6, A8, TT 1.8T; <b>VW:</b> Bora 1.6, 1.8, 2.0 98 / 06, Golf IV 1.6 97 / 04, 1.8 T 97 / 08, Jetta 98 / 05, New Beetle 2.0 98 / 05, Passat 00 / 05, Polo Classic 99 / 01

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	<b>GS8350</b> comprimento do cabo: 83cm	<b>Bosch:</b> 0 261 210 150; <b>GM</b> 93243251, 90510656	<b>GM:</b> Astra 2.0i (SFI) 16V 99>05 / 2.0 GTC Turbo 05> / Turbo / Cabrio 02>05, Astra Sedan 2.0 (SFI) 16V 99>04, Vectra 2.2i 16V (SFI) 97>05, Vectra CD 2.0 16V (SFI) 96>97, Zafira 2.0 16V (SFI) 01>05
	<b>GS8360</b> comprimento do cabo: 62cm	<b>Bosch:</b> 0 261 210 160 ; <b>Fiat:</b> 46470477, 46469866, 46472687, 60814589	<b>ALFA ROMEO:</b> Alfa 146 1.8/2.0 TS 16V 98 > 00, Alfa 147 1.6/2.0 TS 16V 00 >, Alfa 156 SW 2.0 TS 16V 97 > 05, Spider 98 /06 , Alfa 166 98 >; <b>FIAT:</b> Coupé 98 / 00, Marea, Marea Weekend 2.0 , 2.4i 20V Turbo 00 >, Stilo 2.4 (MPI) 20V 01 >
	<b>GS8361</b> comprimento do cabo: 66cm	<b>Bosch:</b> 0 261 210 161, 0 261 210 219; <b>Fiat:</b> 46474583, 46754538, 46754539	<b>FIAT:</b> Doblô 1.3 (MPI) 16V 01 > 06, Palio 1.0 16V, 1.3 16V (Fire) 00 > 03, Palio Weekend 1.0 16V, 1.3 (Fire) 00 > 03, Siena 1.0 16V, 1.3 16V (Fire) 00 > 03, Strada 1.3 16V (Fire) 00 >
	<b>GS8383</b> comprimento do cabo: 33cm	<b>Bosch:</b> 0 261 210 043, 0 261 210 065, 0 261 210 083, 0 261 210 154; <b>Hyundai:</b> 3918022001; <b>KIA:</b> 0K04G-18-891, 0K934-18-891	<b>GM:</b> Omega, Suprema CD 4.1(MPFI) 10/94>12/98, Pick-up C20 (MPFI) 02/92>12/96, Silverado 4.1(MPFI) 01/96>09/97; <b>HYUNDAI:</b> Scoupe 1.5/1.5i/GTI 1.5i Turbo 02/90>04/95; <b>KIA:</b> Sportage 2.0i 16V 4WD FE (16V) 04/94>, Sportage 2.0i 4WD FE 04/94>08/99, Sportage 2.2i 04/94>12/97
	<b>GS8384</b> * Saída para o lado esquerdo	<b>Renault:</b> 7700101969, 7700875184B, 8200436025; <b>Bosch:</b> 0 986 280 411	<b>RENAULT:</b> Clio 1.0 8V 99>, Clio II 1.0 8V, 16V 99>02, Kangoo 1.0 8V/16V 98>, Kangoo 1.6 8V 00>, Scenic 1.6i 96>03, Twingo 1.0 16V 01>07
	<b>GS8389</b> comprimento do cabo: 85cm	<b>GM:</b> 90 508 637, 93 384 389; <b>VDO:</b> 324003008R	<b>GM:</b> Astra, Zafira 2.0L 16V 03>09, Astra, Zafira 2.4L 16V 04>09, Vectra B 16V 97> , Vectra C 2.4 16V 06>
	<b>GS8391</b> comprimento do cabo: 61cm	<b>Fiat:</b> 7 083 327, 7 083 791; <b>GM:</b> 93 393 867; <b>VDO:</b> 324003002	<b>FIAT:</b> Doblô, Idea, Palio, Siena, Stilo, Strada, Weekend 1.8 8V 04>; <b>GM:</b> Corsa, Meriva, Montana 1.8 8V (MPFI - Flexpower) 04>
	<b>GS8405</b>	<b>Bosch:</b> 0.986.280.405; <b>Renault:</b> 7700855719, 7700728637, 7700739794, 7700748442;	<b>Renault:</b> Mégane 1.4/ 1.6 95>, Laguna 93>01, Espace 96>, Twingo 1.2 93>98
	<b>GS8427</b>	<b>Dodge / Jeep:</b> 4713427, 56026882, 56027031, 56029621	<b>JEEP:</b> Cherokee 4.0 i 4x4 1999>2001; <b>DODGE:</b> Dakota 2.5 1995>2003
	<b>GS8433</b>	<b>VW:</b> 032.906.433, 03C.906.433A	<b>VW:</b> Gol, Fox 1.0/ 1.6, Polo 1.6, Golf 1.6, Kombi 1.4, Passat 05>, Jetta 05>, Beetle 11>; <b>Audi:</b> Audi TT 06>, A3, A4, A5 2007>
	<b>GS8450</b>	<b>Chevrolet:</b> 12498965, 10456118; <b>Meat &amp; Doria:</b> 87233; <b>Mobileron:</b> CS-K007	<b>CHEVROLET:</b> Blazer 2.2/2.4 1995>2000, Omega 2.2 MPFI 1995>1998, S10 2.0 EFI 1995>2000, Suprema 2.2 1995>1998 (todos 4Cil e 8V)



FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	<b>GS8471</b>	<b>Mitsubishi:</b> J5T38471; <b>Honda:</b> 37510-59BJ01	<b>HONDA:</b> Civic Touring CVT 1.5 Turbo 2017>
	<b>GS8500</b>	<b>Hyundai:</b> 39180-23500; <b>Kia:</b> 39180-23910	<b>Hyundai:</b> Tucson 2.0 16V 2005>2009, Elantra 1.6/ 1.8/ 2.0 2006>, i30 2.0 2007>; <b>Kia:</b> Sportage 2005>2009, Soul 2010, Cerato 2.0 2006>
	<b>GS8513</b>	<b>Bosch:</b> 0 281 002 513; <b>Iveco:</b> 500374763	<b>IVECO:</b> Daily 40 S 16 2007>, Daily 45 S 14/16 2007> Daily 55 C 16 2007>, Daily 70 C 16 / HD Massimo 2010>, Daily 2000 35 S 14 2007>
	<b>GS8542</b>	<b>GM:</b> 96253542, 96434780; <b>Delphi:</b> SS10894; <b>Magneti Marelli:</b> 064848106010	<b>DAEWOO:</b> Nubira 1.6 1997>2004, Nubira 1.4 2003>2004
	<b>GS8556</b>	<b>Nissan:</b> 01436-00QAC, 23750-00QAG, 23750-00QQE; <b>Renault:</b> 7700108073, 8200468647, 8200647556	<b>Nissan:</b> Kubistar 1.6 16V 2003>; <b>Renault:</b> Clio 1.4 16V 1999>2004, Clio 1.6 16V 1998>, Espace 2.0 16V 1998>2002, Kangoo 1.6 2001>
	<b>GS8571</b>	<b>Mitsubishi:</b> J5T32571, 1865A069	<b>Mitsubishi:</b> Lancer 2008>2011, Outlander 3.0 2008>2011, Outlander Sport 2011
	<b>GS8600</b>	<b>Hyundai/Kia:</b> 39650-42600	<b>Hyundai:</b> H100 2004>; <b>Kia:</b> Bongo
	<b>GS8622</b>	<b>Mitsubishi:</b> MD320622, J5T25082A, PC96	<b>MITSUBISHI:</b> Pajero Sport 3.0 1998>, Pajero Full 3.5, L200 2.5 1997>2011
	<b>GS8643</b>	<b>VW:</b> 041906433A; <b>VDO:</b> 340215002R	<b>VW:</b> Gol GL 2003>2006, Gol GL 2006>2010, Gol G4 2011>2014, Saveiro 2006>2010, Parati 1.6 2011>2013, Fox, Voyage, Golf, Polo, Spacefox (todos com motor AP)
	<b>GS8700</b>	<b>Hyundai:</b> 39310-02700 / 39310-02600	<b>Hyundai:</b> Atos 1.0/1.1 2001>2007, Atos Prime; <b>Kia:</b> Picanto 1.0/1.1 2001>2003
	<b>GS8712</b>	<b>GM:</b> 12567712	<b>Hyundai:</b> Empilhadeira 25L-7M



FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	<b>GS8780</b>	Citroën / <b>Peugeot</b> : 9640627780, 1920FP, 1920EN; Suzuki: 33220-67G01-000	<b>Citroën</b> : C4, C5, C6, Xsara Picasso 2006>; Peugeot: 307, 407 2005>; Suzuki: Gran Vitara
	<b>GS8795</b>	<b>GM</b> : 90412795; <b>Opel</b> : 6238000	<b>GM</b> : Corsa 1.0/ 1.6 16V 93>03, Tigra 1.6 94>
	<b>GS8826</b>	<b>Mitsubishi</b> : MD342826, J5T25871, ADC47205	<b>Mitsubishi</b> : Pajero 2.5 GLX 1990>1999, Pajero 2.5 TDI Sport 2001>2007, L200 2.5 TD 1987>1992, L200 2.5 TD GL/GLS 1996>2007, Montero 3.5 V6 1994>2000, Montero Sport 3.0 V6 1997>2004
	<b>GS8865</b>	<b>Fiat</b> : 55261865	<b>FIAT</b> : Argo HGT 1.8 2017>
	<b>GS8880</b>	Citroën / <b>Peugeot</b> : 9639999880, 9637465980 1920AW; <b>Bosch</b> : 0.986.280.408; <b>Delphi</b> : SS10747-12B1	<b>Citroën</b> : Aircross 1.6 10>, C2 1.6 04>09, C3 1.4/ 1.6 03>, C4 09>, Hoggar 1.4/ 1.6 10>, Xsara 1.6 00>06; Peugeot: 206 1.4/ 1.6 Flex All, 207 1.4/ 1.6 08>13, 307 1.6 00>
	<b>GS8920</b>	Citroën / <b>Peugeot</b> : 9639999980, 1920AV; <b>Delphi</b> : SS10748-12B1	<b>Peugeot</b> : 206 1.4/ 1.6, 306 1.6; Citroën: C3 1.4/1.6, C4 1.4/1.6, Xsara Picasso 1.6
	<b>GS8991</b>	<b>GM</b> : 12590991; <b>Bosch</b> : 0 261 210 274	<b>GM</b> : Captiva 3.0/3.6 V6 2008>, Malibu, Omega Australiano 1999>2005
	<b>GS8992</b>	<b>GM</b> : 12588992	<b>Chevrolet</b> : Agile, Montana, Onix, Prisma, Captiva 2.4 2006, Malibu 2.4 2012

